

MEC LEAD CHARGE BARS FOR SINGLE STAGE PRESS - 7/8OZ LEAD SHOT CHARGE BAR

[Reloading](#) > [Reloading Presses](#) > [Reloading Press Accessories](#)

The MEC Charge Bars allow you to adjust your shot charge and enable you to create the load you desire. Interchanges with the charge bar which is included with your reloading press. Available in both lead and steel styles for single stage and progressive presses.



Attributes

- Name: [7/8OZ LEAD SHOT CHARGE BAR](#)
- Manufacturer: [MEC RELOADING](#)
- Product no.: 749009374
- Mfr. No.: 10030278
- Size: 7/8 oz
- Delivery weight: 0.249kg
- Shipping height: 25mm
- Shipping width: 25mm
- Shipping length: 160mm
- UPC: 098489014342

Item details

Made in USA

Table of Contents

- [Startpage](#)
- [MEC Lead Charge Bars for Single Stage Press Safety Instruction Guide](#)
- [About Us](#)

MEC Lead Charge Bars for Single Stage Press Safety Instruction Guide

Introduction

Thank you for choosing the MEC Lead Charge Bars for your reloading needs. This guide provides essential safety instructions and usage guidelines to ensure your experience is safe and effective. The MEC Charge Bars are designed to help you adjust your shot charge, allowing you to create the load you desire. Please read this manual carefully before using the product.

General Safety Guidelines

To ensure safe use of the MEC Lead Charge Bars, please adhere to the following guidelines:

- Always follow the manufacturer's instructions when using the product.
- Keep the product out of reach of children and vulnerable individuals.
- Inspect the Charge Bar and your reloading press before each use for any signs of damage or wear.
- Use the Charge Bar only with compatible MEC reloading presses.
- Store the Charge Bar in a dry, cool place to prevent rust and deterioration.
- Do not exceed the recommended shot charge limits specified for the Charge Bar.
- Ensure that your workspace is clean and free of obstructions before starting your reloading process.

Specific Safety Precautions for Use

When using the MEC Lead Charge Bars, please observe the following precautions:

- Always wear appropriate safety gear, including safety glasses and hearing protection.
- Avoid wearing loose clothing or jewelry that could get caught in the reloading press.
- Be aware of your surroundings and ensure that no one is in close proximity while operating the reloading press.
- Never attempt to modify or alter the Charge Bar in any way.
- If you experience any issues while using the Charge Bar, stop immediately and consult the troubleshooting section of your reloading press manual.

Instructions for Installation and Usage

Follow these steps for proper installation and usage of the MEC Lead Charge Bars:

1. Installation:

- Ensure that your reloading press is turned off and unplugged before installation.
- Remove the existing charge bar from your reloading press according to the manufacturer's instructions.
- Align the MEC Lead Charge Bar with the mounting points on your reloading press.
- Secure the Charge Bar in place, ensuring it is firmly attached and does not move.

2. Usage:

- Set the desired shot charge on the MEC Lead Charge Bar by adjusting the settings as per the manufacturer's guidelines.
- Load the appropriate materials into the reloading press as instructed in the reloading press manual.
- Operate the reloading press according to the instructions provided, ensuring that all safety

precautions are followed.

- After use, clean the Charge Bar and reloading press to remove any residue or debris.

Disposal Instructions

When disposing of the MEC Lead Charge Bars, please follow these guidelines to ensure safe and environmentally responsible disposal:

- Do not dispose of the Charge Bar in regular household waste.
- Check local regulations for proper disposal methods for metal products.
- If the Charge Bar is damaged or no longer usable, consider recycling it at a designated metal recycling facility.

Contact Information for Further Support

For any safety inquiries or support related to the MEC Lead Charge Bars, please consult the manufacturer's website or customer service for assistance.

Conclusion

By following the safety instructions outlined in this guide, you can ensure a safe and enjoyable experience with your MEC Lead Charge Bars. Remember to stay informed about product recalls and safety updates through the EU's Safety Gate platform. Thank you for prioritizing safety in your reloading activities.

About Us

Brownells Austria

Brownells - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories

www.brownells.at