

# MEC LEAD CHARGE BARS FOR SINGLE STAGE PRESS - MEC RELOADING 2OZ SINGLE STAGE LEAD SHOT CHARGE BAR

[Reloading](#) > [Reloading Presses](#) > [Reloading Press Accessories](#)

The MEC Charge Bars allow you to adjust your shot charge and enable you to create the load you desire. Interchanges with the charge bar which is included with your reloading press. Available in both lead and steel styles for single stage and progressive presses.



## Attributes

- Name: [MEC RELOADING 2OZ SINGLE STAGE LEAD SHOT CHARGE BAR](#)
- Manufacturer: [MEC RELOADING](#)
- Product no.: 749019410
- Mfr. No.: 302200
- Size: 2 oz
- Delivery weight: 0.234kg
- Shipping height: 25mm
- Shipping width: 25mm
- Shipping length: 165mm
- UPC: 098489016049

## Item details

Made in USA

# Table of Contents

- Startpage
- MEC Lead Charge Bars for Single Stage Press Safety Instructions
- About Us

# MEC Lead Charge Bars for Single Stage Press Safety Instructions

## Introduction

Thank you for choosing the MEC Lead Charge Bars for your reloading needs. These charge bars are designed to provide you with the flexibility to adjust your shot charge, allowing you to create the load you desire. This safety instruction guide will help you understand how to use the product safely and effectively, in compliance with the EU General Product Safety Regulation (GPSR).

## General Safety Guidelines

- Always read and understand the instructions before using the product.
- Keep all packaging and instructions for future reference.
- Ensure that the product is used only for its intended purpose.
- Store the charge bars in a safe and dry location, out of reach of children.
- Regularly inspect the charge bars for any signs of damage or wear before use.
- Report any unsafe products or accidents to the appropriate authorities.

## Specific Safety Precautions for Use

- Use the charge bars only with compatible MEC reloading presses.
- Do not attempt to modify the charge bars in any way.
- Wear appropriate safety gear, including eye protection, when reloading.
- Ensure that your workspace is clean and free from distractions while using the charge bars.
- Be aware of the potential hazards associated with handling lead and other materials.
- Follow all local regulations regarding the handling and disposal of lead materials.

## Instructions for Installation and Usage

### 1. Installation:

- Ensure that the reloading press is turned off and unplugged before installation.
- Remove the existing charge bar from the reloading press.
- Align the MEC Lead Charge Bar with the mounting points on the press.
- Secure the charge bar in place according to the manufacturer's instructions.
- Doublecheck that the charge bar is firmly attached before proceeding.

### 2. Usage:

- Set the desired shot charge by adjusting the charge bar according to the guidelines provided.
- Ensure that the reloading press is properly calibrated before use.
- Load the materials into the press as per the instructions.
- Monitor the reloading process closely to ensure safe operation.
- After use, clean the charge bar and surrounding area to prevent contamination.

## Disposal Instructions

- Dispose of any lead materials and packaging in accordance with local regulations.
- Do not throw away lead materials in regular trash.
- Contact local waste management authorities for proper disposal methods for hazardous materials.

## Contact Information for Further Support

For any inquiries regarding the MEC Lead Charge Bars, please refer to the manufacturer's website or customer service resources. Ensure that you have the product information ready for a more efficient response.

By following these safety instructions, you can ensure a safe and effective reloading experience. Thank you for your attention to safety and compliance.

# About Us

## Brownells UK

### **Brownells UK - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories**

Unit 1, Laughing Dog Industrial Estate  
London Road  
Rugby  
Warwickshire  
CV23 9LP

[www.brownells.co.uk](http://www.brownells.co.uk)