

X-SKEL MOUNTS - WARNE MFG. COMPANY 30MM ULTRA HIGH (1.435") 0 MOA MOUNT, BLACK

[Optics & Mounting](#) > [Rings, Mounts & Bases](#) > [Mount Sets](#)

Warne Scope Mounts is excited to introduce their second generation SKEL mount, the X-SKEL. This new MSR mount offers an additional 1" of forward cantilever, and 1 piece clamp design for added strength. The rugged, lightweight design of the X-SKEL maintains our famous Return to Zero capability, and utilizes $\frac{1}{2}$ " hex nuts for rock solid attachment. It features a skeletonized ring body and caps for reduced weight and steel threaded cap inserts for maximum durability. The X-SKEL places your optic at the IDEAL HEIGHT with a generous cantilever for proper eye relief, it will easily accommodate the longer eyepieces found on many of today's scopes. Lightweight, skeletonized aluminum body and caps to reduce overall weight without sacrificing reliability. #8 Torx style fasteners with steel threaded inserts to prevent stripping. Additional 1 Inch cantilever forward design to provide additional eye relief. Places your optic at the Ideal Height for MSR and similar platforms. 1/2" tactical nut attachment, 65 in/lb. of torque is recommended.



Attributes

- Name: [WARNE MFG. COMPANY 30MM ULTRA HIGH \(1.435"\) 0 MOA MOUNT, BLACK](#)
- Manufacturer: [WARNE MFG. COMPANY](#)
- Product no.: 947000384
- Mfr. No.: XSKEL30TW
- Finish: Black
- Scope Tube Diameter: 30mm
- Style: 3-Gun, Competition
- Delivery weight: 0.247kg
- Shipping height: 64mm
- Shipping width: 165mm
- Shipping length: 184mm
- UPC: 656813104895

Item details

Made in USA

Table of Contents

- Startpage
- XSKELETON MOUNTS WARNE MFG. COMPANY 30MM ULTRA HIGH (1.435") 0 MOA MOUNT, BLACK Safety Instruction Guide
- About Us

XSKELE MOUNTS WARNE MFG. COMPANY 30MM ULTRA HIGH (1.435") 0 MOA MOUNT, BLACK

Safety Instruction Guide

Introduction

Thank you for choosing the XSKELE MOUNTS WARNE MFG. COMPANY 30MM ULTRA HIGH Mount. This guide provides essential safety instructions and guidelines to ensure the safe use and installation of your mount. Please read this guide carefully before using the product.

General Safety Guidelines

- Ensure that the mount is compatible with your scope and firearm before installation.
- Always inspect the mount for any damage or defects before use.
- Follow all local laws and regulations regarding firearm accessories.
- Store the mount in a cool, dry place when not in use.
- Keep the mount out of reach of children and vulnerable individuals.
- Report any unsafe products or accidents to the relevant authorities.
- Regularly check for recall updates on the EU's Safety Gate platform.

Specific Safety Precautions for Use

- **Compatibility:** Ensure that the mount is suitable for your 30mm scope.
- **Installation:** Follow the installation instructions carefully to avoid improper setup that could lead to accidents.
- **Torque Specifications:** Use a torque wrench to tighten the tactical nut attachment to 65 in/lb. Do not exceed this torque specification.
- **Eye Relief:** Ensure proper eye relief by adjusting the mount to the ideal height for your specific optics.
- **Weight Considerations:** Be aware of the lightweight design; ensure that your setup remains stable and secure during use.
- **Fasteners:** Regularly check the #8 Torx style fasteners to ensure they are tight and secure.

Instructions for Installation and Usage

1. Preparation:

- Gather all necessary tools, including a torque wrench and #8 Torx driver.
- Ensure that your workspace is clean and free of obstructions.

2. Installation:

- Place the mount on the designated area of your firearm.
- Align the mount with your scope's mounting points.
- Insert the #8 Torx fasteners through the mount into the firearm's rail.
- Use the torque wrench to tighten the fasteners to a torque of 65 in/lb.
- Doublecheck the alignment and ensure that the mount is securely attached.

3. Usage:

- After installation, mount your scope onto the XSKELE.
- Adjust the scope for proper eye relief and ensure it is secure.
- Test the setup at a safe location to ensure stability and functionality.

4. Maintenance:

- Regularly inspect the mount and fasteners for any wear or damage.
- Clean the mount with a soft cloth and avoid using harsh chemicals.

Disposal Instructions

- Dispose of the mount in accordance with local regulations.
- If the mount is damaged or no longer usable, consider recycling metal components where possible.
- Do not dispose of the mount in household waste.

Contact Information for Further Support

For any inquiries or support regarding the XSKELE MOUNTS WARNE MFG. COMPANY 30MM ULTRA HIGH Mount, please refer to the manufacturer's website or customer service resources.

Note: This guide is intended to provide important safety information and instructions for the use of the XSKELE mount. Always prioritize safety and adhere to all local laws and regulations regarding firearm accessories.

About Us

Brownells UK

Brownells UK - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories

Unit 1, Laughing Dog Industrial Estate
London Road
Rugby
Warwickshire
CV23 9LP

www.brownells.co.uk