

SL900 Accessories - Dillon Complete SL900 Powder Measure Assembly

[Reloading](#) > [Reloading Presses](#) > [Reloading Press Accessories](#)

This powder measure assembly is designed for the SL 900 shotshell reloader

NO IMAGE
AVAILABLE

Attributes

- Name: [Dillon Complete SL900 Powder Measure Assembly](#)
- Manufacturer: [DILLON](#)
- Product no.: EU2005578
- Mfr. No.: DI17817
- Delivery weight: 155kg

Table of Contents

- [Startpage](#)
- [Dillon Complete SL900 Powder Measure Assembly Safety Instructions](#)
- [About Us](#)

Dillon Complete SL900 Powder Measure Assembly

Safety Instructions

Introduction

Thank you for choosing the Dillon Complete SL900 Powder Measure Assembly. This product is designed to enhance your reloading experience while ensuring safety and efficiency. Please read this safety instruction guide carefully to understand how to use the product safely and effectively.

General Safety Guidelines

- Always read the user manual before using the product.
- Ensure that the workspace is clean, dry, and free from obstructions.
- Keep the product out of reach of children and pets.
- Inspect the product for any damage or wear before each use.
- Use the product only for its intended purpose as described in this manual.
- In case of any malfunction or abnormal operation, discontinue use immediately and seek assistance.

Specific Safety Precautions for Use

- Ensure that all components are securely attached before operating the powder measure.
- Avoid overfilling the powder measure to prevent spills and potential hazards.
- Use protective eyewear when operating the product to protect against accidental powder spillage.
- Do not use the powder measure in a confined space without adequate ventilation.
- Keep flammable materials away from the work area when using the powder measure.
- Do not attempt to modify or alter any part of the powder measure assembly.

Instructions for Installation and Usage

Installation

1. Unpack the Dillon Complete SL900 Powder Measure Assembly and check for all components.
2. Place the powder measure on a stable, flat surface.
3. Secure the powder measure to the reloader according to the manufacturer's instructions.
4. Ensure that all connections are tight and there are no leaks.

Usage

1. Adjust the powder measure according to the desired load specifications.
2. Fill the powder reservoir with the appropriate powder type.
3. Cycle the reloader to dispense the powder into the shotshell.
4. Monitor the dispensing process to ensure accuracy and safety.
5. After use, empty any remaining powder from the measure and clean it thoroughly.

Disposal Instructions

- Dispose of any unused or expired powder in accordance with local regulations.
- Do not dispose of the product in regular household waste.
- Check with local authorities for specific disposal guidelines for reloading components and equipment.

Contact Information for Further Support

For any questions or concerns regarding the Dillon Complete SL900 Powder Measure Assembly, please contact

your local Dillon representative or authorized dealer for assistance.

Conclusion

We hope that you enjoy using the Dillon Complete SL900 Powder Measure Assembly. By following these safety instructions, you can ensure a safe and effective reloading experience. Always prioritize safety and do not hesitate to seek help if you have any questions or concerns.

About Us

Brownells Italia

Brownells Italia - The shop of the largest dealer of components and accessories for target shooting guns, defense and hunting

**Sede Legale e Operativa **

Brownells Italia Srl

Via Dante Alighieri 163

25068 Sarezzo Bs

P.Iva e C.F. IT02801420981

www.brownells.it