

Lead Sled MAX

[Reloading](#) > [Bullet Casting](#) > [Lead Alloy](#)

Upgrade your shooting setup with the Caldwell Lead Sled MAX—the ultimate shooting rest for precision, control, and recoil reduction. Designed for shooters who demand stability, this universal-fit rest locks in your firearm, allowing you to focus on accuracy without distraction.

Built from premium, heavy-duty materials, the Lead Sled MAX is engineered for durability and reliability when it matters most. Whether you're sighting in, testing loads, or refining your setup, this shooting rest delivers the rock-solid support you need.

NO IMAGE
AVAILABLE

Attributes

- Name: [Lead Sled MAX](#)
- Manufacturer: [CALDWELL](#)
- Product no.: EU2014054
- Mfr. No.: 3004222
- Colour: Black
- Delivery weight: 11.39kg
- Shipping height: 651mm
- Shipping width: 274mm
- Shipping length: 400mm
- UPC: 198700000946

Table of Contents

- Startpage
- Lead Sled MAX Safety Instructions
- About Us

Lead Sled MAX Safety Instructions

Introduction

Thank you for choosing the Caldwell Lead Sled MAX. This shooting rest is designed to enhance your shooting experience by providing stability, control, and recoil reduction. To ensure safe and effective use of this product, please read and follow these safety instructions carefully.

General Safety Guidelines

- Always ensure the firearm is unloaded when attaching or detaching it from the Lead Sled MAX.
- Use the Lead Sled MAX only for its intended purpose as a shooting rest.
- Keep the Lead Sled MAX out of reach of children and unauthorized users.
- Regularly inspect the Lead Sled MAX for any signs of wear or damage before each use.
- Store the Lead Sled MAX in a dry and secure location when not in use.

Specific Safety Precautions for Use

- Ensure that the shooting area is clear of obstructions and bystanders before shooting.
- Always wear appropriate eye and ear protection while using the Lead Sled MAX.
- Be aware of your surroundings and ensure that you are in a safe environment for shooting.
- Adjust the Lead Sled MAX securely to prevent any movement during shooting.
- Do not exceed the weight limit specified in the product specifications to avoid instability.

Instructions for Installation and Usage

1. Setup:

- Place the Lead Sled MAX on a flat, stable surface.
- Adjust the front and rear supports to fit your firearm securely.
- Lock the firearm in place using the provided locking mechanism.

2. Shooting:

- Ensure the firearm is pointed in a safe direction.
- Confirm that the shooting area is clear.
- Load the firearm only when you are ready to shoot.
- After shooting, always unload the firearm before making any adjustments to the Lead Sled MAX.

3. Maintenance:

- Clean the Lead Sled MAX regularly to maintain its performance.
- Inspect all components for wear and tear, and replace any damaged parts immediately.

Disposal Instructions

- Dispose of the Lead Sled MAX in accordance with local regulations.
- If the product is no longer usable, consider recycling materials where possible.
- Do not dispose of the Lead Sled MAX in regular household waste.

Contact Information for Further Support

For any inquiries or concerns regarding safety, please contact the manufacturer directly through their official channels. Ensure you have the product details ready for reference.

Thank you for your attention to these safety instructions. Enjoy your shooting experience with the Caldwell Lead Sled MAX!

About Us

Brownells UK

Brownells UK - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories

Unit 1, Laughing Dog Industrial Estate
London Road
Rugby
Warwickshire
CV23 9LP

www.brownells.co.uk