

BORE-MAX SPEED BRUSH - REAL AVID 375 CALIBER BORE-MAX SPEED BRUSH

[Gun Cleaning & Chemicals](#) > [Brushes & Bore Snakes](#) > [Bore Brushes](#)

The Bore-Max Speed Brush is a component of the Bore-Max Speed Clean System for faster and easier bore cleaning. Carbon build-up not only affects performance and accuracy, but also causes degradation of the bore. Carbon build-up also insulates the copper fouling in the bore making it difficult to dissolve and remove with bore solvent. Using a bore brush to remove this carbon build-up is the best way to tackle the job. In order to achieve maximize effectiveness, there needs to be an optimal balance between bristle density and bristle flexibility. Having too few bristles is a waste of time and too many won't provide enough flexibility to navigate the lands and grooves of the bore. The bristle configuration of the Bore-Max Speed Brush provides maximum scrubbing density removing more carbon with each pass and getting maximum results faster.



Attributes

- Name: [REAL AVID 375 CALIBER BORE-MAX SPEED BRUSH](#)
- Manufacturer: [REAL AVID](#)
- Product no.: 100047676
- Mfr. No.: AVBMSB375
- Caliber: 375 Caliber (.375)
- Style: Rifle
- Delivery weight: 0.045kg
- Shipping height: 13mm
- Shipping width: 70mm
- Shipping length: 159mm
- UPC: 813119013430

Table of Contents

- Startpage
- BOREMAX SPEED BRUSH SAFETY INSTRUCTIONS
- About Us

BOREMAX SPEED BRUSH SAFETY INSTRUCTIONS

Introduction

Thank you for choosing the BOREMAX SPEED BRUSH. This product is designed to provide effective bore cleaning for your firearms. To ensure safe and effective use, please read and follow the safety instructions outlined in this guide.

General Safety Guidelines

- Always use the BOREMAX SPEED BRUSH in accordance with the manufacturer's instructions.
- Keep the product out of reach of children and vulnerable individuals.
- Inspect the brush before each use for any signs of damage or wear. Do not use if damaged.
- Avoid using the brush with excessive force, as this may damage the bore or the brush itself.
- Store the brush in a dry place away from direct sunlight and extreme temperatures.
- Be aware of any potential hazards associated with cleaning solvents and ensure proper ventilation when using them.

Specific Safety Precautions for Use

- Wear protective eyewear when using the BOREMAX SPEED BRUSH to prevent debris from entering your eyes.
- Use gloves to protect your hands from cleaning solvents and any sharp edges on the brush.
- Ensure that the firearm is unloaded and pointed in a safe direction before cleaning.
- Do not use the BOREMAX SPEED BRUSH on a hot bore. Allow the firearm to cool down before use.
- Follow the instructions for your specific firearm to avoid damaging the bore.

Instructions for Installation and Usage

1. Preparation

- Ensure the firearm is unloaded and in a safe location.
- Gather necessary materials: BOREMAX SPEED BRUSH, cleaning solvent, and protective gear (gloves and eyewear).

2. Using the BOREMAX SPEED BRUSH

- Apply a suitable bore cleaning solvent to the brush.
- Insert the brush into the bore from the chamber end (if applicable) and push it through to the muzzle end.
- Use a smooth, steady motion to scrub the bore, ensuring the bristles make contact with the surface.
- Repeat as necessary, depending on the level of carbon buildup.
- After cleaning, remove the brush and clean it according to the manufacturer's instructions.

3. Postusage Care

- Clean the brush with solvent and allow it to dry completely before storage.
- Store the brush in a protective case or designated storage area.

Disposal Instructions

- Dispose of the BOREMAX SPEED BRUSH in accordance with local regulations.
- Do not dispose of the brush in regular household waste if it is contaminated with hazardous materials.

- Check with local waste management authorities for proper disposal methods.

Contact Information for Further Support

For additional support regarding the BOREMAX SPEED BRUSH, please refer to the manufacturer's website or contact the customer service department. Always ensure you have the product details on hand for any inquiries.

Thank you for your attention to these safety instructions. By following these guidelines, you can ensure a safe and effective cleaning experience with your BOREMAX SPEED BRUSH.

About Us

Brownells UK

Brownells UK - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories

Unit 1, Laughing Dog Industrial Estate
London Road
Rugby
Warwickshire
CV23 9LP

www.brownells.co.uk