

CZ SHADOW 2 LEUPOLD DELTAPOINT PRO SIGHT MOUNT - EGW CZ SHADOW 2 VORTEX LEUPOLD DELTAPOINT PRO SIGHT MOUNT

[Optics & Mounting](#) > [Rings, Mounts & Bases](#) > [Handgun Bases](#)

Material: 7075 Aluminum Coating: Matte Black Hardcoat Overall Length: 1.604" Overall Width: .99" Mounting Hardware: (2) 6-32 Button Head Screws, (2) 6-32 Flat Head Screws, (1) 6-32 Set Screw Red Dot Fitment: Vortex Viper/Venom, Burris FastFire, Crimson Trace CTS-1200, CTS-1300, Docter EGW's red dot sights are meant to be installed from the left to the right (with the muzzle facing forward). The dovetail has a progressive taper to allow for easier install. Simply remove the rear sight on your gun and replace it with our mount in order to mount your Vortex Viper/Venom, Burris FastFire, or Docter red-dot sight. No alterations are required. You can take our mount off and replace your rear sight at any time. Mounting hardware included. Installation Instructions Remove the rear sight* Install the EGW Sight Mount in the dovetail Tighten set screw (if applicable) Place the red dot sight on the EGW Sight Mount (placing a small piece of paper between the red dot sight and the sight mount will make for easier removal and will keep Loctite off of the red dot sight.) Apply blue Loctite to the provided mounting screws Torque mounting screws to 15in/lbs 2 Button Head Cap Screws - Provided for Vortex Viper and Venom Sights 2 Flat Head Cap Screws - Provided for Burris FastFire and Docter Sights The screws that are included with this mount require a 5/64" allen wrench for installation.



Attributes

- Name: [EGW CZ SHADOW 2 VORTEX LEUPOLD DELTAPOINT PRO SIGHT MOUNT](#)
- Manufacturer: [EGW](#)
- Product no.: 296000546
- Mfr. No.: 49397
- Colour: Black
- Material: Aluminum
- Model: 75,Shadow,Shadow 2,SP-01 Shadow
- Number of Bases: 1-Piece
- Style: Tactical
- Weapon type: CZ
- Delivery weight: 0.034kg
- Shipping height: 25mm
- Shipping width: 89mm
- Shipping length: 140mm
- UPC: 841370116652

Item details

Made in USA

Table of Contents

- Startpage
- CZ Shadow 2 Leupold DeltaPoint Pro Sight Mount Safety Instruction Guide
- About Us

CZ Shadow 2 Leupold DeltaPoint Pro Sight Mount Safety Instruction Guide

Introduction

Thank you for purchasing the CZ Shadow 2 Leupold DeltaPoint Pro Sight Mount. This guide provides essential safety instructions and information to ensure the safe and effective use of your product. Please read this document carefully before installation and use.

General Safety Guidelines

To ensure your safety and the proper functioning of the CZ Shadow 2 Leupold DeltaPoint Pro Sight Mount, please adhere to the following guidelines:

- Ensure that the product is used only for its intended purpose.
- Regularly inspect the sight mount for any signs of wear or damage.
- Keep the mount and all associated tools out of reach of children.
- Always follow local laws and regulations regarding firearm accessories.
- Use only the recommended mounting hardware and tools for installation.
- Avoid using the product in extreme temperatures or conditions that may affect its performance.

Specific Safety Precautions for Use

When using the CZ Shadow 2 Leupold DeltaPoint Pro Sight Mount, please observe the following precautions:

- Check that the mount is securely attached before each use.
- Do not modify the mount or the firearm in any way that could impair safety.
- Ensure that the red dot sight is properly aligned and mounted before use.
- Use caution when handling firearms and always treat them as if they are loaded.
- If you experience any issues with the mount or sight, discontinue use immediately and seek assistance.

Instructions for Installation and Usage

Follow these steps for the correct installation and usage of your CZ Shadow 2 Leupold DeltaPoint Pro Sight Mount:

1. **Remove the rear sight** from your firearm.
2. **Install the EGW Sight Mount** in the dovetail from left to right, ensuring the muzzle is facing forward.
3. **Tighten the set screw** (if applicable) to secure the mount.
4. **Place the red dot sight** on the EGW Sight Mount. For easier removal, place a small piece of paper between the red dot sight and the sight mount to prevent Loctite from adhering to the sight.
5. **Apply blue Loctite** to the provided mounting screws.
6. **Torque the mounting screws** to 15 in/lbs:
 - 2 Button Head Cap Screws Provided for Vortex Viper and Venom Sights
 - 2 Flat Head Cap Screws Provided for Burris FastFire and Docter Sights
7. Ensure that the screws are tightened securely using a 5/64" allen wrench.

Disposal Instructions

When disposing of the CZ Shadow 2 Leupold DeltaPoint Pro Sight Mount, please follow these guidelines:

- Dispose of the product in accordance with local regulations regarding electronic waste and materials.
- Do not dispose of the mount in regular household waste.
- Consider recycling options where available to minimize environmental impact.

Contact Information for Further Support

For any questions or concerns regarding the CZ Shadow 2 Leupold DeltaPoint Pro Sight Mount, please refer to the manufacturer's contact information provided in the product packaging or visit the manufacturer's website for additional resources.

Thank you for your attention to these safety instructions. Your safety is our priority, and we wish you a safe and enjoyable experience with your new sight mount.

About Us

Brownells UK

Brownells UK - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories

Unit 1, Laughing Dog Industrial Estate
London Road
Rugby
Warwickshire
CV23 9LP

www.brownells.co.uk