

INSTANT INDICATORS - REDDING INSTANT INDICATOR/222 REMINGTON

[Reloading](#) > [Measuring Tools](#) > [Case Gauges & Headspace Tools](#)

REDDING INSTANT INDICATORS The Redding Instant Indicator is a precision made tool that allows a hand loader to quickly compare headspace and bullet seating depth within .001". The Instant Indicator provides an extremely quick method for comparing bullets, seating depths, fired cases, sized cases, trim lengths and loaded ammunition for uniformity. Easily perform any of the following tasks:

FEATURES: Sort bullets for uniformity Sort cases fired in two or more rifles Sort sized cases for uniformity Set up sizing die correctly Compare sized cases to fired cases to determine the amount of headspace Check uniformity of shoulder bump Check bullet seating depth uniformity Sort loaded ammunition for uniformity Determine when cases need trimming Check trim length uniformity Instructions Included Supplied with one bore diameter bushing, surface contactor, shoulder contactor, headspace gauge and complete instructions. The Instant Indicator fits the cartridge listed in the description, however it may be used for a family of cartridges with the same shoulder angle.



Attributes

- Name: [REDDING INSTANT INDICATOR/222 REMINGTON](#)
- Manufacturer: [REDDING](#)
- Product no.: 749007154
- Mfr. No.: 17109
- Cartridge: 222 Remington
- Delivery weight: 0.363kg
- Shipping height: 38mm
- Shipping width: 112mm
- Shipping length: 152mm
- UPC: 611760171093

Item details

Made in USA

Table of Contents

- Startpage
- Redding Instant Indicator Safety Instruction Guide
- About Us

Redding Instant Indicator Safety Instruction Guide

Introduction

Thank you for choosing the Redding Instant Indicator. This precision tool is designed for hand loaders to compare headspace and bullet seating depth quickly and accurately. To ensure your safety and the optimal performance of this product, please carefully read and follow the safety instructions outlined in this guide.

General Safety Guidelines

- Ensure that the Redding Instant Indicator is used in accordance with the manufacturer's instructions.
- Always handle the tool with care to avoid injury or damage.
- Keep the tool out of reach of children and vulnerable individuals.
- Regularly inspect the tool for any signs of wear or damage before use.
- If the tool is damaged, discontinue use immediately and seek a replacement.
- Report any unsafe conditions or incidents to the relevant authorities.

Specific Safety Precautions for Use

- **Personal Protective Equipment (PPE):** Always wear safety glasses and gloves when using the Redding Instant Indicator to protect against potential debris or sharp edges.
- **Work Environment:** Use the tool in a welllit and clean area to avoid accidents. Ensure that the workspace is free from clutter.
- **Proper Handling:** Always handle the tool by its designated parts. Avoid placing fingers near sharp edges or moving parts.
- **Avoid Overloading:** Do not exceed the specified limits of the tool. Use it only for the intended cartridge types as stated in the product specifications.
- **Calibration:** Regularly check the calibration of the tool to ensure accurate measurements. Follow the instructions provided for calibrating the device.
- **Storage:** Store the tool in a dry and secure location when not in use. Avoid exposure to extreme temperatures or humidity.

Instructions for Installation and Usage

1. Preparation:

- Before using the Redding Instant Indicator, read all instructions carefully.
- Ensure that you have the necessary components: bore diameter bushing, surface contactor, shoulder contactor, headspace gauge, and complete instructions.

2. Setting Up the Tool:

- Select the appropriate bore diameter bushing for the cartridge you are working with.
- Attach the surface contactor and shoulder contactor securely to the tool.
- Insert the headspace gauge according to the manufacturer's guidelines.

3. Using the Tool:

- To compare bullets, seating depths, or cases, follow these steps:
 - Place the item to be measured in the tool.
 - Adjust the settings as necessary to ensure accurate readings.
 - Read the measurement displayed and compare it with your specifications.

- Repeat the process for each item you wish to measure.

4. PostUse:

- After completing your measurements, clean the tool to remove any debris or residue.
- Store the tool in its designated case or area to prevent damage.

Disposal Instructions

- Dispose of the Redding Instant Indicator according to local regulations regarding electronic and precision tools.
- Do not dispose of the tool in regular household waste. Instead, consider recycling options available in your area.

Contact Information for Further Support

For any questions or concerns regarding the Redding Instant Indicator, please consult the manufacturer's website or customer support for assistance. It is advisable to keep this instruction guide for future reference.

By following these safety instructions, you will ensure a safe and effective experience with your Redding Instant Indicator. Thank you for your attention to these guidelines.

About Us

Brownells UK

Brownells UK - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories

Unit 1, Laughing Dog Industrial Estate
London Road
Rugby
Warwickshire
CV23 9LP

www.brownells.co.uk