

SINGLE STAGE PRESS LEAD SKEET SPECIAL CHARGE BAR - MEC RELOADING 3/4OZ SINGLE STAGE LEAD SKEET SPECIAL CHARGE BAR

[Reloading](#) > [Reloading Presses](#) > [Reloading Press Accessories](#)

Single stage lead shot bars designed for your competition needs.



Attributes

- Name: [MEC RELOADING 3/4OZ SINGLE STAGE LEAD SKEET SPECIAL CHARGE BAR](#)
- Manufacturer: [MEC RELOADING](#)
- Product no.: 749019436
- Mfr. No.: 30234SS
- Size: 3/4 oz
- Delivery weight: 0.249kg
- Shipping height: 25mm
- Shipping width: 25mm
- Shipping length: 165mm
- UPC: 098489016889

Item details

Made in USA

Table of Contents

- Startpage
- Safety Instruction Guide for SINGLE STAGE PRESS LEAD SKEET SPECIAL CHARGE BAR
- About Us

Safety Instruction Guide for SINGLE STAGE PRESS LEAD SKEET SPECIAL CHARGE BAR

Introduction

Thank you for choosing the SINGLE STAGE PRESS LEAD SKEET SPECIAL CHARGE BAR by MEC RELOADING. This product is designed to meet your competition needs in reloading lead shot. To ensure your safety and the safety of others, please read this guide carefully before using the product.

General Safety Guidelines

- Ensure that you read and understand all safety instructions before use.
- Always use the product in accordance with the manufacturer's guidelines.
- Keep the product out of reach of children and vulnerable individuals.
- Regularly inspect the product for any signs of wear or damage.
- Report any unsafe conditions or incidents to the appropriate authorities.
- Stay informed about product recalls via the EU's Safety Gate platform.

Specific Safety Precautions for Use

- Always wear safety glasses and appropriate protective gear when using the reloading press.
- Do not overload the charge bar beyond its specified capacity of 3/4 oz.
- Ensure that the workspace is clean and free from any obstructions.
- Avoid using the product in wet or damp conditions to prevent electrical hazards.
- Do not attempt to modify or tamper with the charge bar.
- Follow all local regulations regarding the handling and use of reloading equipment.

Instructions for Installation and Usage

1. Installation:

- Place the SINGLE STAGE PRESS LEAD SKEET SPECIAL CHARGE BAR on a stable, flat surface.
- Ensure that it is securely attached to the reloading press according to the manufacturer's instructions.
- Check all connections and fittings to ensure they are tight and secure.

2. Usage:

- Before starting, ensure that you have all necessary materials and tools at hand.
- Load the charge bar with the appropriate amount of lead shot (3/4 oz).
- Follow the reloading press instructions for operating the machinery safely.
- Monitor the reloading process closely and stop immediately if any irregularities occur.
- After use, clean the charge bar to maintain its condition and functionality.

Disposal Instructions

- Dispose of any waste materials according to local regulations.
- Do not dispose of lead shot or any other components in regular trash.
- Contact local waste management services for guidance on the safe disposal of hazardous materials.

Contact Information for Further Support

For any questions or concerns regarding the SINGLE STAGE PRESS LEAD SKEET SPECIAL CHARGE BAR, please refer to the manufacturer's customer service or support resources. Ensure that you have your product details available for assistance.

By following these guidelines, you can ensure a safe and effective experience with your SINGLE STAGE PRESS LEAD SKEET SPECIAL CHARGE BAR. Thank you for your attention to safety.

About Us

Brownells UK

Brownells UK - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories

Unit 1, Laughing Dog Industrial Estate
London Road
Rugby
Warwickshire
CV23 9LP

www.brownells.co.uk