

X-SKEL MOUNTS - WARNE MFG. COMPANY 1" ULTRA HIGH (1.435") 0 MOA MOUNT, BLACK

[Optics & Mounting](#) > [Rings, Mounts & Bases](#) > [Mount Sets](#)

Warne Scope Mounts is excited to introduce their second generation SKEL mount, the X-SKEL. This new MSR mount offers an additional 1" of forward cantilever, and 1 piece clamp design for added strength. The rugged, lightweight design of the X-SKEL maintains our famous Return to Zero capability, and utilizes 1/2" hex nuts for rock solid attachment. It features a skeletonized ring body and caps for reduced weight and steel threaded cap inserts for maximum durability. The X-SKEL places your optic at the IDEAL HEIGHT with a generous cantilever for proper eye relief, it will easily accommodate the longer eyepieces found on many of today's scopes. Lightweight, skeletonized aluminum body and caps to reduce overall weight without sacrificing reliability. #8 Torx style fasteners with steel threaded inserts to prevent stripping. Additional 1 Inch cantilever forward design to provide additional eye relief. Places your optic at the Ideal Height for MSR and similar platforms. 1/2" tactical nut attachment, 65 in/lb. of torque is recommended.



Attributes

- Name: [WARNE MFG. COMPANY 1" ULTRA HIGH \(1.435"\) 0 MOA MOUNT, BLACK](#)
- Manufacturer: [WARNE MFG. COMPANY](#)
- Product no.: 947000379
- Mfr. No.: XSKE1TW
- Finish: Black
- Scope Tube Diameter: 1"
- Style: 3-Gun, Competition
- Delivery weight: 0.252kg
- Shipping height: 64mm
- Shipping width: 184mm
- Shipping length: 168mm
- UPC: 656813104833

Item details

Made in USA

Table of Contents

- Startpage
- XSKELE Mounts Safety Instruction Guide
- About Us

XSKELE Mounts Safety Instruction Guide

Introduction

Thank you for choosing the XSKELE Mounts by Warne MFG. Company. This guide provides essential safety instructions to ensure the proper and safe use of your scope mount. Please read this manual carefully before installation and use to understand the safety precautions and guidelines.

General Safety Guidelines

- Ensure that the product is used only for its intended purpose as a scope mount for firearms.
- Always follow local laws and regulations regarding the use of firearms and firearm accessories.
- Keep the product out of reach of children and unauthorized users.
- Regularly inspect the mount for any signs of wear or damage before each use.
- Avoid using the product if it shows signs of damage or if any components are missing.
- Be aware of your surroundings when using firearms equipped with the XSKELE mount.

Specific Safety Precautions for Use

- Always wear appropriate eye and ear protection when using firearms.
- Ensure that the firearm is unloaded when installing or adjusting the mount.
- Use only compatible scopes with a 1 inch tube diameter as specified in the product description.
- Do not exceed the recommended torque of 65 in/lb. for the tactical nut attachment.
- Regularly check the fasteners to ensure they are secure and have not loosened during use.
- Be cautious of the cantilever design; ensure it does not obstruct your line of sight or cause imbalance.

Instructions for Installation and Usage

1. Preparation

- Gather all necessary tools, including a $\frac{1}{2}$ " socket wrench and #8 Torx fasteners.
- Ensure the firearm is unloaded and pointed in a safe direction.

2. Installation Steps

- Locate the mounting base on your firearm where the scope mount will be attached.
- Align the XSKELE mount with the mounting base, ensuring the skeletonized ring body is properly positioned.
- Insert the #8 Torx fasteners into the mount holes and handtighten initially.
- Use the $\frac{1}{2}$ " socket wrench to tighten the fasteners to the recommended torque of 65 in/lb. Do not overtighten.
- Attach your scope to the mount, ensuring it is securely fastened.

3. Usage

- After installation, check the alignment of the scope and adjust as necessary.
- Always verify the zeroing of your scope before heading to the range or field.
- Maintain a consistent check on the mount and scope integrity during use.

Disposal Instructions

- Dispose of the product in accordance with local regulations regarding electronics and metal waste.
- Recycle any components that are recyclable, such as aluminum and steel parts.
- Do not dispose of the product in household waste.

Contact Information for Further Support

For any safety inquiries or further assistance, please refer to the manufacturer's contact information provided with your purchase.

Conclusion

By following these safety guidelines and instructions, you can ensure the safe and effective use of your XSKE^L Mounts. Always prioritize safety and responsible firearm handling. Thank you for your commitment to safety and for choosing Warne MFG. Company.

About Us

Brownells UK

Brownells UK - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories

Unit 1, Laughing Dog Industrial Estate
London Road
Rugby
Warwickshire
CV23 9LP

www.brownells.co.uk